



## Brush motor Fuse My50

Machine model:	My50
Subject:	Brush motor Fuse
Since the serial number:	213002974
Modification date:	18.03.2013
TM Reference:	355

### Description

In order to prevent the premature action of the fuse in the start-up transients of the motor brush in case the machine is used with buffer, the 30A fuse has been replaced by a 50A one. This avoids the intervention of the fuse even for start-up transients in excess of those at standard conditions

### Removed

Code	Quantity	Description
409607	1	MAXIFUSE 30A

### Added

Code	Quantity	Description
409612	1	MAXIFUSE 50A

<p>Fuse 30A</p>	<p>Fuse 50A</p>

**Note:** The new fuse can be installed on previous models as well